

<b>de</b>	Montageanleitung
<b>en</b>	Mounting instructions
<b>fr</b>	Instructions de montage
<b>sv</b>	Monteringsinstruktion
<b>nl</b>	Montage-aanwijzing
<b>it</b>	Istruzioni di montaggio
<b>fi</b>	Asennusohje
<b>es</b>	Instrucciones de montaje
<b>da</b>	Monteringsvejledning


**Tauchtemperaturfühler**  
**Immersion temperature sensor**  
**Sonde de température à plongeur**  
**Dykgivare**  
**Dompeltemperatuuropnemer**  
**Termosonda di mandata a immersione**  
**Vesianturi**  
**Sonda de temperatura de inmersión**  
**Dykrørsføler**

# QAE3010...





# QAE3075...



QAE3010...




QAE3075...



**de** Maßbilder  
**en** Dimensions  
**fr** Encombres

**sv** Måttuppgifter  
**nl** Maatschets  
**it** Ingombri

**fi** Mittapiirros  
**es** Dimensiones  
**da** Målskitse



Typ	A [mm]
<b>QAE3010.010</b>	100
<b>QAE3010.016</b>	160
<b>QAE3075.010</b>	100
<b>QAE3075.016</b>	160

Maße in mm  
Dimensions in mm  
Dimensions en mm  
Mått i mm  
Maten in mm  
Dimensioni in mm  
Mitat mm  
Dimensiones en mm  
Mål i mm